









Safe Work Practice GUARDING OF MACHINERY AND MOVING PART

Potential Hazards (Risk Priority MEDIUM)

- Moving parts
- Cuts, abrasions
- Severing, shearing and stabbing
- All personnel must ensure they have been appropriately trained by their supervisor.

Required Personal Protective Equipment and Devices

Foot Protection	Hearing Protection	High Visibility	Head Protection	Eye Protection	Face Protection	Hand Protection	Protective Clothing
							

Safe Work Practice

Machinery must have proper guards for moving parts and all guards in place before being operated. Moving machinery and equipment connected to any power source must be shut down or disconnected before repairs are made. If this is not possible, an approved safer operating procedure must be followed.

This equipment must be tagged and locked out before any work is performed.

Removing guards from reciprocating or rotating machinery except for temporary removal for maintenance or repairs, is strictly prohibited. Violation of this is grounds for disciplinary action up to and including discharge.

Created by: Dean Neuburger

Date: 2022-13-06

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, shut the equipment off immediately and follow the lock out procedure.

REPORT ANY HAZARDOUS SITUATION TO YOUR SUPERVISOR IMMEDIATELY

This must be reviewed any time the task, equipment, or materials change and at minimum, every three years.